| Group | Item Description | Unit Qty in Kit |
|---------------|-------------------------------------|-----------------|
| TOOLS + LONGS | linear rods 8mm | 2 |
| TOOLS + LONGS | hex Key, micro | 1 |
| TOOLS + LONGS | hex key, med | 1 |
| TOOLS + LONGS | hex key, large | 1 |
| TOOLS + LONGS | Screwdriver phillips | 1 |
| TOOLS + LONGS | Marker, permanent fineliner | 1 |
| TOOLS + LONGS | Ruler, 30cm metric | 1 |
| TOOLS + LONGS | wrenches | 2 |
| TOOLS + LONGS | threaded rod 5/16" x 12" | 1 |
| SOFT PARTS | buzzer | 1 |
| SOFT PARTS | Wire harness | 1 |
| SOFT PARTS | 9g servo | 1 |
| SOFT PARTS | servo extension wire | 1 |
| SOFT PARTS | Jumper Wires | 5 |
| SOFT PARTS | limit switch | 1 |
| SOFT PARTS | rubber feet stick on | 6 |
| SOFT PARTS | cable ties | 25 |
| SOFT PARTS | sticky tack | 4 |
| SOFT PARTS | timing belt GT2 | 1 |
| MOTOR BAG | stepper motor, nema 17 with cable | 2 |
| MOTOR BAG | motor cork mount | 2 |
| IN BOX | Bed Plate | 1 |
| IN BOX | ALL 3D PRINTS | 1 |
| HARD PARTS | heatsink | 1 |
| HARD PARTS | linear bearing 8mm | 3 |
| HARD PARTS | shoulder bolt 8mm dia | 2 |
| HARD PARTS | hex bolt 5/16"x 1.5" fully threaded | 1 |
| HARD PARTS | shoulder bolt 6mm dia | 2 |
| HARD PARTS | linear bearing 6mm | 2 |
| HARD PARTS | pulley toothed driving | 2 |
| HARD PARTS | pulley idler GT2 | 1 |
| HARD PARTS | plastite screws short | 25 |
| HARD PARTS | plastite screws long | 4 |
| HARD PARTS | 3mmx18mm cap screw | 12 |
| HARD PARTS | 3mm nut | 12 |
| HARD PARTS | 3mm x 30mm cap screw | 1 |
| HARD PARTS | 3mm x10mm flat head screw | 4 |
| HARD PARTS | nut standard 5/16 | 7 |
| HARD PARTS | nut nylock 5/16 | 1 |
| HARD PARTS | spring compression | 1 |
| HARD PARTS | magnets | 6 |
| CABLES | USB Extension Cable for arduino | 1 |
| CABLES | Power Supply Wall Wart | 1 |
| CABLES | On/Off Switch Cable | 1 |




| Group | Item Description | Unit Qty in Kit |
|-------------|--|-----------------|
| ENGRAVER | 6x magnets | 6 |
| ENGRAVER | shield Transparent | 1 |
| ENGRAVER | longer Screw for plastic | 1 |
| ENGRAVER | Shorter screw for plastic | 4 |
| ENGRAVER | engraver Bit ball end diamond | 5 |
| PCB IN CUP | arduino Nano CNC Kit | 1 |
| PCB IN CUP | USB-B to USB-C short cable | 1 |
| PCB IN CUP | Paper Cup 8 oz | 1 |
| SPARE PARTS | disc magnet 8x3mm | 2 |
| SPARE PARTS | Shorter screw for plastic | 4 |
| SPARE PARTS | longer Screw for plastic | 1 |
| SPARE PARTS | 3mmx18mm screw | 1 |
| SPARE PARTS | 3mm nut | 2 |
| SPARE PARTS | 3mm x 30mm screw | 1 |
| SPARE PARTS | 3mm x10mm flat head screw | 1 |
| SPARE PARTS | nut 5/16 standard | 1 |
| SPARE PARTS | sticky foot | 2 |
| SPARE PARTS | cable ties | 25 |
| SPARE PARTS | jumpers | 5 |
| SPARE PARTS | super glue | 1 |
| SPARE PARTS | Printed (Knob round + knob hex + grip + cable mount) | 1 |
| SPARE PARTS | sticky tack | 4 |
| SPARE PARTS | servo 9g | 1 |
| SPARE PARTS | Sticker, CylinDraw Logo, 4"x2" | 1 |

The following information is for reference only. <mark>Be aware that Graham Research LLC makes the potentiometer adjustment for you in all of our kits and you do not need to do this! We mark the potentiometer with a marker.</mark>


Adjusting Drive current


- Step one is connect motors, drivers, & Arduino, then power it on.
- Never disconnect the stepper motor cable while the power is connected.
- A4988 = stepper motor driver. We need to set **VREF**, the voltage between the potentiometer and GND as measured with a potentiometer on the next page.
- The calculation formula of the current upper limit is I=VREF/(8*Rs)
- Rs is the reference resistor; the reference resistor for this module is 0.05Ω. VREF=I*8*0.05=0.4*I
- The current limit of our motors is 1.5A (so VREF=1.5*0.4, that is, 0.6V MAX, so we target 0.55V for a safety factor.)
- •
- Bonus info: When using the driver in full-step mode, the current through each coil is limited to approximately 70% of the set current limit. This means that you would need to set the current limit 40% higher or 1.4 A in full-step mode. When using microstepping, the formula above applies.

Note orientation of drivers & nano on the pcb!



Now you will need to measure the reference voltage (Vref) between the two points marked on the picture below (GND and the potentiometer) and adjust it to the value you calculated.





Note we use X axis for the rotational axis and Y axis for the linear axis. Z axis driver is left open.

Stuff we do for you: The servo motor is connected to a 3-wire ribbon cable extension, and then that extension is connected to 3 individual jumper wires. We also tune the resistance trimmers on the stepper drivers to supply the appropriate current, then superglue them in place & mark them with a line. (we do this for you in all our kits because the consequences of doing this wrong can be disastrous)

-The jumpers underneat the stepper drivers configure the microstepping steps per rotation. The rotational axis (x-axis) will keep all 3 jumpers. The Linear axis (y-axis) ONLY keeps the center jumper. (The reason is to tradeoff some resolution we don't need to get more speed we do need!)

- A0 (abort)= unconnected
- A1 (hold)= unconnected
- A2 (resume)= unconnected
- A3(cool) = unconnected
- A4 (SDA)= unconnected
- A5 (SCL) = unconnected
- A6 = unconnected
- A7 servo2 = unconnected
- D0 (RX) =unconnected
- D1 (TX) = unconnected
- D2 (Xstep)= (part of drivers)
- D3~(Ystep)= (part of drivers)
- D4 (Zstep)= unconnected
- D5~(Xdir) = (part of drivers)
- D6~(Ydir)= (part of drivers)
- D7 (Zdir)= unconnected
- D8 (enable) = (part of drivers)
- D9~ (X+,X-) = unconnected
- D10~ (Y+ & Y-)= Limit switch red wire (normally closed leg)
- D11~(Z- & Z+) = Servo Yellow wire (sig)
- D12 = Buzzer+
- D13 = Arduino Embedded LED
- GND = Buzzer-, Servo Brown Wire, Limit switch black center wire.
- 5V = Servo Red (Center wire) (I use the available 5v pin next to A6)