


Rev 0.2
Fixed the pull down resistors.
For 0.1 need to leave R2/R3
and add the R2/R3/R5 pull
downs onto the DB9 connections.
Fixed direction of audio
Fix swapped pin 1/11 on 273 so that iowr was reset



Sheet: /		
File: ps2port.sch		
Title:		
Size: A3	Date:	Rev:
KiCad E.D.A. eeschema 5.1.4-3.fc30		Id: 1/1