



R4 for Pulse skipping (better ripple)
R5 for Burst Mode (better efficiency)

Label node is added to expose copper without attaching it to ground or another node (for pretty label)

Sheet: /		File: PO-PSU.sch	
Title:		Rev:	
Size: A4	Date:	KiCad E.D.A. kicad 4.0.6	
Id: 1/1			