



Table 1. Stepping Format

MODE 2	MODE 1	MODE 0	STEP MODE
0	0	0	Full step (2-phase excitation) with 71% current
0	0	1	1/2 step (1-2 phase excitation)
0	1	0	1/4 step (W1-2 phase excitation)
0	1	1	8 microsteps/step
1	0	0	16 microsteps/step
1	0	1	32 microsteps/step
1	1	0	32 microsteps/step
1	1	1	32 microsteps/step

Drawing by Trigoprint Ltd. Switzerland
creation date: 19.11.2015

Attribution-NonCommercial-ShareAlike 4.0 International (CC BY-NC-SA 4.0)