









Smart Response XE Terminal Reverse Engineering
 This schematic is probably not 100% accurate. Decoupling capacitors are missing.
 Schéma du terminal Smart Response XE
 Le schéma n'est probablement pas exacte à 100%. Condensateurs de découplage absents

Sheet: /	
File: Smart_Response_XE.sch	
Title: SMART Response XE - CPU	
Size: A4	Date: 2019-11-03
KiCad E.D.A. kicad 5.1.4-e60b26684ubuntu18.04.1	Rev: 1.0
	Id: 1/2

Enter key is routed but has no dome so there is no physical enter key
 La touche enter est routée mais le dome est absent donc il n'y a pas de touche enter physique



Smart Response XE Terminal Reverse Engineering
 This schematic is probably not 100% accurate. Decoupling capacitors are missing.
 Schéma du terminal Smart Response XE
 Le schéma n'est probablement pas exact à 100%. Condensateurs de découplage absents

Sheet: /keyboard/
 File: keyboard.sch

Title: SMART Response XE – Keyboard

Size: A4 Date: 2019-11-03
 KiCad E.D.A. kicad 5.1.4-e60b26684ubuntu18.04.1

Rev: 1.0
 Id: 2/2