



Prototype board errors:  
 U6 was wrongly using IOWR not SLOWR (needs a wire fix)  
 74HC573's should be 74HC574s (swapped)

Sheet: /		Date:	
File: slave.sch		Rev:	
Size: A4	KiCad E.D.A. eeschema 5.1.5-1.fc31		Id: 1/1