

program a regulated fast charge current via the ISET resistor setting charge resistor at ISET1 for fast charge max. 1000mA Iout = 540 / Rset = 540/560 = 964 mA

